

EAST Search History**EAST Search History (Prior Art)**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L20	16	"4877645"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2010/11/17 23:00
L21	16	"4877645"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/11/17 23:00
L22	28	"3995772"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/11/17 23:02
L23	0	mark\$4 with cable with multi near nozzl\$4	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/11/17 23:03
L24	0	(mark\$4 or paint) with cable with multi near nozzl\$4	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/11/17 23:03
L25	0	(mark\$4 or paint) with cable with multinozzl\$4	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/11/17 23:03
L26	0	(mark\$4 or paint) with cable same multinozzl\$4	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/11/17 23:04

L27	0	(mark\$4 or paint) with cable same multi near nozsl\$4	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/11/17 23:04
L28	98	(mark\$4 or paint) with cable with nozsl\$4	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/11/17 23:04
L29	98	(mark\$4 or paint) with cable with nozzles	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/11/17 23:05
L30	24	(mark\$4 or paint) with cable with nozzles	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2010/11/17 23:05
L31	25	(mark\$4 or paint or dye or pigment) with cable with nozzles	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2010/11/17 23:10
L32	7484	(mark\$4 or paint or dye or pigment) with nozzles	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2010/11/17 23:11
L33	97	(mark\$4 or paint\$4 or dye or pigment) with nozzles and (mark\$4 or paint\$4 or dye or pigment) with cable	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2010/11/17 23:12
S1	1	10/523975	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/04/21 17:57

S2	16	"4503437"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/04/21 18:02
S3	2044	((101/171/) or (101/211/) or (101/34/) or (101/117/) or (101/177/)).CCLS.	USPAT; USOCR	OR	OFF	2010/04/21 18:09
S4	24	S3 and cable	USPAT	OR	OFF	2010/04/21 18:09
S5	4572	yazaki.as.	USPAT	OR	OFF	2010/04/21 18:11
S6	288	S5 and color\$4	USPAT	OR	OFF	2010/04/21 18:12
S7	93	(mark\$4 or label\$4) with(cable or wire) and (multi\$4 near (color or nozzle))	USPAT	OR	OFF	2010/04/21 18:16
S8	328	(mark\$4 or label\$4) with(cable or wire) and (multi\$4 near (color or nozzle))	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/04/21 18:16
S9	295	(mark\$4 or label\$4) with(cable or wire) and (multi\$4 near (color))	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/04/21 18:16
S10	603	(cable or wire)with mark and nozzl\$4	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/04 18:22
S11	197	(cable or wire)with mark and nozzl\$4 and color	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/04 18:22

S12	1	10/523975	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/04 18:23
S13	15	"4877645"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/04 18:27
S14	623	(427/117).CCLS.	USPAT; USOCR	OR	OFF	2010/05/04 18:49
S15	92	S14 and gas	USPAT	OR	OFF	2010/05/04 18:49
S16	8	S14 and gas and color	USPAT	OR	OFF	2010/05/04 18:50
S17	15	S14 and air and color	USPAT	OR	OFF	2010/05/04 18:51
S19	3	S14 and air with (press\$4 or spray) and color	USPAT	OR	OFF	2010/05/04 18:52
S20	9	"5444466"	USPAT	OR	OFF	2010/05/04 18:53
S21	13	"4877645"	USPAT	OR	OFF	2010/05/05 13:18
S22	15	"4877645"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/05 13:18
S23	3	S22 and valve	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/05 13:18
S24	1	10/523975	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/05 13:21
S25	4578	yazaki.as.	USPAT	OR	OFF	2010/05/05 13:42

S26	2631	S25 and wire	USPAT	OR	OFF	2010/05/05 13:43
S27	3	S25 and wire and valve and spout\$4	USPAT	OR	OFF	2010/05/05 13:43
S28	6	"3176650"	USPAT	OR	OFF	2010/05/05 13:54
S29	6	"3176650"	USPAT	OR	OFF	2010/05/05 13:54
S30	1	10/825220	USPAT	OR	OFF	2010/05/05 13:57
S31	1241	((11/314/) or (118/325/) or (118/113/)).COLS.	USPAT; USOCR	OR	OFF	2010/05/05 13:58
S32	1666	((427/117/) or (427/424/)).COLS.	USPAT; USOCR	OR	OFF	2010/05/05 13:59
S33	0	("111and12").PN.	USPAT; USOCR	OR	OFF	2010/05/05 13:59
S34	74	S31 and S32	USPAT	OR	OFF	2010/05/05 14:00
S35	2518	color\$4 near wheel	USPAT	OR	OFF	2010/05/05 14:16
S36	89	color\$4 near wheel. ti.	USPAT	OR	OFF	2010/05/05 14:16
S37	3	color\$4 near wheel. ti. and pressure and valve	USPAT	OR	OFF	2010/05/05 14:17
S38	3	color\$4 near wheel. ti. and pressure and valve	USPAT	OR	ON	2010/05/05 14:18
S39	26	color\$4 near wheel. ti. and press\$4 and valve	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/05 14:18
S40	1	color\$4 near wheel. ti. and press\$4 and valve and(cable or wire)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/05 14:18

S41	576	color\$4 near wheel and press\$4 and valve	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/05 14:21
S42	11	"2989943"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/05 14:24
S43	11	"3021815"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/05 14:27
S44	308	"24923"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/05 14:30
S45	2385	spray\$3 same nozzle \$4 with (reservoir or tank or container) with valve and (press\$4 with gas or air)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/06 16:18
S49	2079	spray\$3 with nozzle \$4 with (reservoir or tank or container)with valve and (press\$4 with (gas or air))	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/06 16:19
S50	451	spray\$3 with nozzle \$4 with (reservoir or tank or container)with valve and (press\$4 with (gas or air)) and (paint\$\$ or color)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/06 16:20

S51	293	spray\$3 with nozzle \$4 with (reservoir or tank or container)with valve and (tank or reservoir or container)with(press \$4 with (gas or air)) and (paint\$\$ or color)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/06 16:21
S52	293	spray\$3 with nozzle \$4 with (reservoir or tank or container)with valve and (tank or reservoir or container)with(press \$4 with (gas or air)) and (paint\$4 or color)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/06 16:21
S53	10	spray\$3 with nozzle \$4 with (reservoir or tank or container)with valve and (tank or reservoir or container)with(press \$4 with (gas or air)) and (paint\$4 or color)with (wire or cable)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/06 16:21
S54	18	"2,812,211"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/06 16:29
S55	2	spray\$3 with nozzle \$4 with (reservoir or tank or container)with valve with between and (tank or reservoir or container)with(press \$4 with (gas or air)) and (paint\$4 or color)with (wire or cable)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/06 16:33

S56	61	spray\$3 with nozzle \$4 with (reservoir or tank or container)with valve with between and (tank or reservoir or container)with(press \$4 with (gas or air)) and (paint\$4 or color)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/06 16:40
S57	1	spray\$3 with nozzle \$4 with (reservoir or tank or container)near2 valve near2 between and (tank or reservoir or container)with(press \$4 with (gas or air)) and (paint\$4 or color)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/06 16:46
S58	5	"3068838"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/05/06 17:47
S59	24	"3995772"	USPAT	OR	OFF	2010/11/09 14:54
S60	16	"4503437"	USPAT	OR	OFF	2010/11/09 14:55
S61	18	"4503437"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/11/09 14:55
S62	1043	(mark\$4 or paint \$4) with (cable or wire) and "45" near degree	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/11/09 16:25

S63	120	(mark\$4 or paint \$4) near (cable or wire) and "45" near degree	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/11/09 16:26
S64	15	(mark\$4 or paint \$4) near (cable or wire) and "45" near degree and nozzle	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/11/09 16:26

11/18/2010 12:13:57 AM

C:\ Documents and Settings\ ttadayyoneslami\ My Documents\ EAST\ Workspaces
\10523975-2.wsp